




Groomer Gauge



Groomer Gauge



1. While on a flat surface, loosen button screw on back of digital indicator to rotate flat tip front to back.



2. Loosen button screw inside handle to rotate flat tip left and right.



3. Once tip is flat in both directions, tighten both screws.



4. While still on a flat surface, turn indicator on and zero.